

# UNDERWATER BRIDGE INSPECTION REPORT

---

STRUCTURE NO. 69536

TWP NO. 415

OVER THE

CHANNEL AT LAKE VERMILLION

DISTRICT 1 - ST. LOUIS COUNTY

---



PREPARED FOR THE  
MINNESOTA DEPARTMENT OF TRANSPORTATION

BY  
COLLINS ENGINEERS, INC.

JOB NO. 3512 (CEI 12)

MINNESOTA DEPARTMENT OF TRANSPORTATION  
UNDERWATER BRIDGE INSPECTION

REPORT SUMMARY:

The substructure units inspected at Bridge No. 69536, Piers 1 and, 2 were found to be in good condition with no defects of structural significance observed. Since the previous inspection, the deterioration on the steel pipe piles has increased, however, there was still no appreciable loss of original section of integrity. The channel bottom appeared to be stable with no evidence of significant scour or appreciable changes since the previous inspection.

INSPECTION FINDINGS:


- (A) The steel pipe piles exhibited 50 to 100 percent coating failure and surface corrosion from 6 inches above the waterline to 6 inches below the waterline.
- (B) The steel pipe piles exhibited 50 to 75 percent coating failure with heavy nodular corrosion, with nodules that were 1 to 1.5 inches in diameter and with typical pitting of 1/32 inch in depth and up to 1/16 inch deep, from 6 inches below the waterline to the channel bottom.

RECOMMENDATIONS:

- (A) Reinspect the submerged substructure units at the normal maximum recommended (NBIS) interval of five (5) years.


I hereby certify that this plan, specification, or report was prepared by me or under my direct supervision and that I am a duly Licensed Professional Engineer under the laws of the State of Minnesota.

Daniel G. Stromberg

  
Date 6/30/2004 Registration No. 21491

Respectfully submitted,

COLLINS ENGINEERS, INC.



Daniel G. Stromberg  
Registered Professional  
Engineer, State of Minnesota

MINNESOTA DEPARTMENT OF TRANSPORTATION  
UNDERWATER BRIDGE INSPECTION

1. BRIDGE DATA

Bridge Number: 69536

Feature Crossed: Channel at Lake Vermillion

Feature Carried: TWP No. 415

Location: District 1 - St. Louis County

Bridge Description: The superstructure is a three span, multiple prestressed concrete girder bridge supporting a reinforced concrete deck. The superstructure is supported by two reinforced concrete abutments and two steel shell pile bent piers. The abutments are founded on spread footings keyed into bedrock. The piers are numbered 1 and 2 starting from the west end of the bridge.

2. INSPECTION DATA

Professional Engineer Diver: Daniel G. Stromberg  
State of Minnesota, P.E., No. 21491

Dive Team: Michelle D. Koerbel, Matthew J. Lengyel

Date: August 29, 2002

Weather Conditions: Cloudy,  $\pm 65^{\circ}$  F

Underwater Visibility:  $\pm 3.0$  Feet

Waterway Velocity: Negligible/None

3. SUBSTRUCTURE INSPECTION DATA

Substructure Inspected: Piers 1 and 2.

General Shape: Rectangular reinforced concrete pile cap with rounded ends supported by four concrete-filled steel shell piles.

Maximum Water Depth at Substructure Inspected: Approximately 5.0 feet.

4. WATERLINE DATUM

Water Level Reference: The top of the pier cap on the south side of Pier 1.

Water Surface: The waterline was approximately 8.3 feet below reference.  
Assumed Waterline Elevation = 91.7.

5. NBIS CODING INFORMATION (Minnesota specific codes are used for 92B and 113)

Item 60: Substructure: Code 7


Item 61: Channel and Channel Protection: Code 8

Item 92B: Underwater Inspection: Code B/08/02

Item 113: Scour Critical Bridges: Code I/92

Bridge is scour critical because abutment or pier foundation is rated as unstable due to observed scour at bridge site.

\_\_\_\_\_ Yes  X  No



TYPICAL END VIEW OF PIERS

#### GENERAL NOTES:

- Piers 1 and 2 were inspected underwater.
- At the time of inspection on August 29, 2002, the waterline was located approximately 8.3 feet below the top of the cap at the south end of Pier 1. Since insufficient bridge elevation information was available a reference elevation of 100.0 was assumed. Based on the assumed reference the waterline elevation was 91.7.
- Soundings indicate the water depth at the time of inspection and are measured in feet.
- Soundings were taken parallel to the bridge at 1/4 point intervals between the substructure units.

#### INSPECTION NOTES:

- The channel bottom material typically consisted of firm sand with scattered riprap up to 18 inches in diameter and a maximum probe rod penetration of 1 to 3 inches.
- Both shorelines were well protected with 12 to 36 inch diameter riprap material along the banks.
- The steel pipe piles exhibited 50 to 100 percent coating failure and surface corrosion from 6 inches above the waterline to 6 inches below the waterline.
- The steel pipe piles exhibited 50 to 75 percent coating failure from 6 inches below the waterline to the channel bottom with heavy nodular corrosion, ranging in size from 1 to 1.5 inches in diameter. Rust nodules exhibited typical pitting of 1/32 inches in depth and up to 1/16 inches deep.

#### Legend


- 4.0 Sounding Depth from Waterline (8/29/02)  
-3.5 Sounding Depth from Waterline (8/23/97)
- Concrete Filled Steel Pipe Pile

#### MINNESOTA DEPARTMENT OF TRANSPORTATION UNDERWATER BRIDGE INSPECTION


STRUCTURE NO. 69536  
OVER THE CHANNEL, LAKE VERMILLION  
DISTRICT I, ST. LOUIS COUNTY

#### INSPECTION AND SOUNDING PLAN

Drawn By: PRH	 <b>COLLINS ENGINEERS, INC.</b> 300 W. WASHINGTON, STE. 600 CHICAGO, ILLINOIS 60606 (312) 704-9300	Date: AUG. 2002
Checked By: MDK		Scale: NTS
Code: 351200I2		Figure No.: 1



NORTH FASCIA PROFILE



SOUTH FASCIA PROFILE

Note:  
Refer to Figure 1 for General Notes.

**MINNESOTA  
DEPARTMENT OF TRANSPORTATION  
UNDERWATER BRIDGE INSPECTION**

STRUCTURE NO. 69536  
OVER THE CHANNEL, LAKE VERMILLION  
DISTRICT 1, ST. LOUIS COUNTY

**NORTH AND SOUTH  
FASCIA PROFILES**

Drawn By: PRH  
Checked By: MDK  
Code: 35I200I2



**COLLINS ENGINEERS, INC.**  
300 W. WASHINGTON, STE. 600  
CHICAGO, ILLINOIS 60606  
(312) 704-9300

Date: AUG. 2002  
Scale: 1"=40'  
Figure No.: 2





Photograph 1. Overall View of Structure, Looking South.



Photograph 2. View of Pier 1, Looking Northeast.





Photograph 3. View of Pier 2, Looking Northeast.



Photograph 4. View of Typical Corrosion of the Steel Pipe Piles, Looking Northeast.



MINNESOTA DEPARTMENT OF TRANSPORTATION  
OFFICE OF BRIDGES AND STRUCTURES  
DAILY DIVING REPORT

INSPECTORS: Collins Engineers, Inc.

DATE: August 29, 2002

ON-SITE TEAM LEADER: Daniel G. Stromberg, P.E.

BRIDGE NO: 69536

WEATHER: Cloudy, " 65° F

WATERWAY CROSSED: Channel at Lake Vermillion

DIVING OPERATION: X

SCUBA

SURFACE SUPPLIED AIR

OTHER

PERSONNEL: Michelle D. Koerbel, Matthew J. Lengyel

EQUIPMENT: Scuba, U/W Light, Scraper, Lead Line, Probe Rod, Camera

TIME IN WATER: 9:10 A.M.

TIME OUT OF WATER: 9:40 A.M.

WATERWAY DATA: VELOCITY Negligible/None

VISIBILITY " 3.0 feet

DEPTH 5.0 feet maximum at Pier 2

ELEMENTS INSPECTED: Piers 1 and 2

REMARKS: Overall, the steel pipe piles were in good condition with 50 to 100 percent coating failure at the surface and 50 to 75 percent coating failure below water, with heavy nodular corrosion having nodules ranging from 1 to 1.5 inches in diameter. There was pitting beneath the nodular corrosion with 1/32 typical to 1/16 inch maximum penetration.

FURTHER ACTION NEEDED: \_\_\_\_\_ YES  X  NO

Reinspect the submerged substructure units at the normal maximum recommended (NBIS) interval of five (5) years.

MINNESOTA DEPARTMENT OF TRANSPORTATION  
OFFICE OF BRIDGES AND STRUCTURES

UNDERWATER INSPECTION CONDITION RATING FORM

BRIDGE NO. 69536  
INSPECTORS Collins Engineers, Inc.  
ON-SITE TEAM LEADER Daniel G. Stromberg, P.E. 21491  
WATERWAY CROSSED Channel, Lake Vermillion

INSPECTION DATE August 29, 2002  
NOTE: USE ALL APPLICABLE CONDITION  
DEFINITIONS AS DEFINED IN THE MINNESOTA  
RECORDING AND CODING GUIDE INCLUDING  
GENERAL, SUBSTRUCTURE, CHANNEL AND  
PROTECTION, AND CULVERTS AND WALL  
DEFINITIONS TO COMPLETE THIS FORM.

CONDITION RATING

UNIT REFERENCE NO.	UNIT DESCRIPTION	MAXIMUM DEPTH OF WATER	SUBSTRUCTURE						CHANNEL					GENERAL					
			PILING	COLUMNS, SHAFTS, OR FACES*	FOOTINGS	DISPLACEMENT	OTHER (BRACING)	OVERALL SUBSTRUCTURE CONDITION CODE*	SCOUR	EMBANKMENT EROSION	EMBANKMENT PROTECTION	OTHER (DRIFT/DEBRIS)	OVERALL CHANNEL & PROTECTION CONDITION	CONCRETE	STEEL	TIMBER	LOSS OF SECTION	PREVIOUS REPAIR OR MAINTENANCE	OTHER
		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18
	Pier 1	3.5'	7	N	N	9	N	7	8	N	8	N	8	N	7	N	7	N	N
	Pier 2	5.0'	7	N	N	9	N	7	8	N	8	N	8	N	7	N	7	N	N

\*UNDERWATER PORTION ONLY

REMARKS: Overall, the steel pipe piles were in good condition with 50 to 100 percent coating failure at the surface and 50 to 75 percent coating failure below water, with heavy nodular corrosion having nodules ranging from 1 to 1 .5 inches in diameter. There was pitting beneath the nodular corrosion with 1/32 typical to 1/16 inch maximum penetration.

NOTES: ATTACH SKETCHES AS NEEDED, IDENTIFY REMARK BY REFERRING TO UNIT REFERENCE NO. AND REMARK NO.  
USE GENERAL SECTION TO IDENTIFY OVERALL PRESENCE OF SPALLS, CRACKS, CORROSION, ETC.